

AD-A074 756

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON  
NATIONAL DAM SAFETY PROGRAM. KIRKWOOD LAKE DAM (NJ-00399). DELA--ETC(U)  
AUG 79 F K JOLLS

F/G 13/2

DACW61-79-C-0011


UNCLASSIFIED

NL

1 OF 1  
AD  
A074 756



END  
DATE  
FILMED  
11-79  
DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

Approved for public release;  
distribution unlimited

AD A U 7 4 7 5 6

DELAWARE RIVER BASIN  
COOPER RIVER, CAMDEN COUNTY  
NEW JERSEY

KIRKWOOD LAKE DAM  
NJ 00399


LEVEL #

6 PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM.

Kirkwood Lake Dam (NJ-00399), Delaware  
River Basin. Cooper River, Camden County,  
New Jersey. Phase 1 Inspection Report.

9 Final rept.,

10 F. Keith /Jolls



15 DACW61-79-C-0011

DEPARTMENT OF THE ARMY

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania

DDC FILE COPY

11 August, 1979

12 63

410 891

79 10 05 060

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00399	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Kirkwood Lake Dam Camden County, N.J.		5. TYPE OF REPORT & PERIOD COVERED  FINAL
7. AUTHOR(s)  Jolls, F. Keith P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Louis Berger & Associates 100 Halstead Ave. East Orange, N.J. 07019		8. CONTRACT OR GRANT NUMBER(s)  DACW61-79-C-0011
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE August 1979
		13. NUMBER OF PAGES 35
		15. SECURITY CLASS. (of this report)  Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES  Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Kirkwood Lake Dam, N.J.                      Dams Spillways    Visual Inspection Slopes    Structural Analysis Outlet Works                                      National Dam Inspection Act Report		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		





IN REPLY REFER TO  
NAPEN-D

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

NOTES ON FORM	
NTIS G.L. & I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	<input type="checkbox"/>
By _____	
Distribution/ _____	
Availability Codes _____	
Dist. _____	Availand/or special _____

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, NJ 08621

25 SEP 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Kirkwood Lake Dam in Camden County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Kirkwood Lake Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 26 percent of the Spillway Design Flood--SDF - would overtop the dam. (The SDF, in this instance, is the One Hundred Year Flood). To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980.

b. Within thirty days from the date of approval of this report, the ownership and responsibility for maintenance should be clarified as a collapse could present a legal problem regarding responsibility.

c. The following remedial actions should be completed within one year from the date of approval of this report:

(1) The low level outlet should be made operable so that the reservoir can be drained.

NAPEN-D

Honorable Brendan T. Byrne

(2) The downstream slopes of the dam embankment in the vicinity of the bridge wingwalls should be regraded, compacted and topped with suitable slope protection.

(3) The trees should be removed from the dam crest in the vicinity of the spillway and the disturbed areas regraded, compacted and seeded.

(4) Heavy stone should be placed in the downstream stilling basin in selected areas to prevent further scouring and preclude the undermining of the bridge structure.

(5) Patch the spalled and deteriorated concrete surfaces and stone masonry of the bridge walls.

(6) The crest width should be increased at each side of the spillway and seeded or protected from surface erosion.

(7) The owners should upgrade the operation and maintenance procedures for the dam by utilizing a check list for periodic inspections and instituting a system of record keeping for severe storms.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman James J. Florio of the First District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.


Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

NAPEN-D

Honorable Brendan T. Byrne

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

1 Incl  
As stated

Copies furnished:  
Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Management  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625



KIRKWOOD LAKE DAM (NJ00399)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 1 May 1979 by Louis Berger & Associates, Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Kirkwood Lake Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate since 26 percent of the Spillway Design Flood--SDF - would overtop the dam. (The SDF, in this instance, is the One Hundred Year Flood). To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980.

b. Within thirty days from the date of approval of this report, the ownership and responsibility for maintenance should be clarified as a collapse could present a legal problem regarding responsibility.

c. The following remedial actions should be completed within one year from the date of approval of this report:

(1) The low level outlet should be made operable so that the reservoir can be drained.

(2) The downstream slopes of the dam embankment in the vicinity of the bridge wingwalls should be regraded, compacted and topped with suitable slope protection.

(3) The trees should be removed from the dam crest in the vicinity of the spillway and the disturbed areas regraded, compacted and seeded.

(4) Heavy stone should be placed in the downstream stilling basin in selected areas to prevent further scouring and preclude the undermining of the bridge structure.

(5) Patch the spalled and deteriorated concrete surfaces and stone masonry of the bridge walls.

(6) The crest width should be increased at each side of the spillway and seeded or protected from surface erosion.

(7) The owners should upgrade the operation and maintenance procedures for the dam by utilizing a check list for periodic inspections and instituting a system of record keeping for severe storms.

APPROVED: 

JAMES G. TON

Colonel, Corps of Engineers  
District Engineer

DATE: 22 Sep 1979



PHASE 1 REPORT  
NATIONAL DAM INSPECTION PROGRAM

Name of Dam Kirkwood Lake  
Fed. ID# 00399


State Located New Jersey  
County Located Camden  
Coordinates Lat. 3950.2 - Long 7500.1  
Stream Cooper River  
Date of Inspection 1 May 1979

ASSESSMENT OF  
GENERAL CONDITIONS

Kirkwood Lake is assessed to be in an overall fair structural condition and is recommended to be downgraded from a high hazard to a significant hazard category. Overtopping of the dam would not appreciably increase the danger of loss of life or property damage as the downstream flood plain is, for the most part, uninhabited. No detrimental findings were covered to render a questionable judgement as to the structural stability. Remedial actions recommended to be undertaken in the near future are to 1) regrade slopes adjacent to wingwalls, 2) remove root systems on the embankment slopes by the spillway, 3) place riprap in the downstream channel, 4) patch the concrete and masonry surfaces of the bridge substructure, and 5) rebuild the dam crest width at each side of the spillway and seed or provide erosion protection.


The ownership of the dam could not be determined.

----- This dam has an inadequate spillway, being able to accomodate only 25% of the spillway design flood.



F. Keith Jolls P.E.  
Project Manager





OVERVIEW OF KIRKWOOD LAKE DAM

MAY, 1979

## TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	
Overall View of Dam	
Table of Contents	
Preface	
Section 1 - Project Information	1-4
Section 2 - Engineering Data	5-6
Section 3 - Visual Inspection	7-9
Section 4 - Operational Procedures	10
Section 5 - Hydraulic/Hydrologic	11-12
Section 6 - Structural Stability	13-14
Section 7 - Assessments/Recommendations/ Remedial Actions	15-16

## FIGURES

Figure 1 - Regional Vicinity Map
Figure 2 - General Plan
Figure 3 - Plan of Spillway
Figure 4 - Spillway Sections

## APPENDIX

Check List - Visual Inspection	
Check List - Engineering Data	
Photographs	
Check List - Hydrologic and Hydraulic Data	
Computations	A1-A14



## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
NAME OF DAM: KIRKWOOD LAKE DAM FED ID# NJ 00399

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with Contract FPM-36 between Louis Berger & Associates, Inc. and the State of New Jersey and its Department of Environmental Protection, Division of Water Resources. The State, in turn, is under agreement with the U.S. Army Engineer District, Philadelphia, to have this inspection performed.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Kirkwood Lake Dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The dam at Kirkwood Lake is a straight 250 foot long, ill-defined low earth embankment with a rectangular concrete box spillway built into an ancient stone masonry bridge abutment near the left end of the dam. The hydraulic drop at the 11' x 19' spillway is 8.5' and discharges into an irregular stilling basin adjacent to the R.O.W. of the PATCO commuter railroad (Pennsylvania Reading Seashore Railroad).

b. Location

Kirkwood Lake Dam is located on the Cooper River 0.30 mile northeast of the intersection of White Horse Road (Rt. 673) and White Horse Pike (Route U.S. 30) on the municipal boundary between the Township of Voorhees and Borough of Lindenwold, Camden County.

c. Size Classification

The maximum height of the dam is 12.5 feet and the maximum storage is estimated to be 226 acre-feet. Therefore the dam is placed in the small size category as defined by the Recommended Guidelines for Safety Inspection of Dams (storage less than 1,000 acre-feet and height less than 40 feet).

d. Hazard Classification

Based upon the Corps of Engineers criteria and the fact that in the event of a failure, little damage would be inflicted on downstream development or endanger human life, the classification is recommended to be downgraded to a significant hazard. Below the dam, Cooper River flows under White Horse Road in an elliptical corrugated culvert which would act as a hydraulic restriction to downstream flooding. The roadway embankment (some 100 feet downstream) would actually function as a back-up dam. Its average height is 10 to 20 feet above the study dam crest. Further downstream, the flood plain is only sparsely developed with most facilities above expected high water, except for a sewage treatment plant. However, a failure of the spillway could block the elliptical CMP under White Horse Road and possibly flood the adjacent railroad trackage of the PATCO commuter line. In view of the potential damage to this utility, the significant hazard classification is hereby recommended.

e. Ownership

The legal owner is presently unknown. Both the municipalities of Voorhees and Lindenwold and Camden County disclaim ownership. According to Dam Application 31-35 (dated 5/20/43) the structure is owned by the Kirkwood Lake Colony Club of Kirkwood N.J. but they could not be located. In 1966, a Mr. Albert N. Brewin wrote to the Department of Conservation and Economic Development requesting permission to make minor repairs but there is no record that he owns the dam.

f. Purpose of dam

The dam was built to impound a recreational lake within a lakeside residential development.

g. Design and Construction History

It is unknown when the earliest dam at this site was initially constructed. The present spillway was rebuilt by the Lakeside Park Development Company in 1941 after the dam embankment had been breached by the flood of September 1, 1940. Historical records indicate the spillway was relocated from the right to the left end of the dam and the dam was initially constructed in 1931 or 1932 by the American Ice Co. The 1941 reconstruction plans were prepared by Paul X. Blattler, P.E. #1977 but only indicated the spillway details. Except for periodic replacement of timber stoplogs, the basic configuration has apparently not changed since 1941.

h. Normal Operating Procedures

The dam spillway functions as an uncontrolled weir with no attempt to control the reservoir level except during periods of cleaning and repair (see Section 4).

1.3 PERTINENT DATA

- a. Drainage Area - 5.14 sq. miles
- b. Total spillway capacity at maximum pool elevation 918 cfs.
- c. Elevation (above M.S.L.)
  - Top of dam - 59.81
  - Recreation Pool - 55.81
  - Streambed at center line of dam - 47.3<sub>+</sub>
- d. Reservoir
  - Length of Recreation Pool - 3700 feet
  - Length of Maximum pool - 4200 feet
- e. Storage
  - Recreation Pool - 92 acre-feet
  - Top of Dam - 226 acre-feet
- f. Reservoir Surface
  - Top of dam - 36 acres
  - Recreation pool - 31 acres
- g. Dam
  - Type : Earth embankment with 3 sided concrete drop inlet spillway.
  - Length - 250 feet
  - Top Width - 20 feet
  - Height - 12.5 feet
  - Side Slopes - 2H:IV<sub>+</sub>
  - Zoning - Unknown
- h. Diversion and Regulating Tunnel
  - None
- i. Spillway
  - Type - Three-sided overflow concrete box
  - Length of weir - 41 feet
- j. Regulating Outlets - removable stoplogs in spillway (3' x 3' and 3' x 5') See Figure 4.



## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

The only information available for design review were microfilm records and the single drawing prepared in 1941 for reconstruction of the spillway. This indicated the geometry and details of this wall section but revealed nothing of the earlier highway bridge to which the spillway is connected. Also located were several hydraulic calculations which were reviewed (as summarized in Section 5). No boring logs or information were available although it was indicated on the 1940 Dam Application that the underlying foundation material is a fine sand with a trace of clay and a dark impervious green marl. The general area is surrounded by stratified marine sands known as Kirkwood deposits which contain fine micaceous quartz sand with varying amounts of silt. The depth to bedrock in this area is greater than 100 feet.

### 2.2 CONSTRUCTION

Little information was obtained regarding the 1941 construction. From the various reports at that time, the construction appeared to have been accomplished substantially in agreement with the design. There have been no other major structural modifications since the 1941 work.

### 2.3 OPERATION

There is no day-to-day operation at this dam as the timber stoplogs are kept continuously closed under normal conditons. The lake level is uncontrolled except during periods of maintainence.

### 2.4 EVALUATION

#### a. Availability

Sufficient engineering data is vailable (except for the old spillway bridge) to ascertain the structural stability and assess the dam's



overall safety. No data was located upon which to base an assessment of the embankment permeability but in light of the modest height, the dike structure appears to be stable.

b. Adequacy

It is felt that the available data is sufficient to allow the rendering of the following assessment contained in Section 7.

c. Validity

The validity of the information available is not challenged and is accepted without recourse to further investigation.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

The visual inspection was conducted on May 1, 1979 at which time the inflow was producing a modest discharge over the spillway. The physical condition of the embankment appeared stable and the inspection team was primarily concerned with the deteriorated condition of the old spillway bridge.

#### b. Dam

The embankment appears to have supported a local street in earlier times and is fairly wide in comparison to its height. However, it is only about 13 feet wide at the spillway. The old stone masonry bridge at the spillway previously supported a steel I-beam and timber deck (now removed). The upstream edge of the dam crest is lined with small trees and the entire downstream slope area to the right of the spillway has been backfilled to only one foot below crest grade. There is a considerable amount of scouring at the ends of the wingwalls. The left abutment zone contains a much newer concrete headwall and storm drain discharge pipes from the railroad switching yards on the south side of the lake. There has apparently been little upkeep of the embankment slopes for many years. Much of the dam crest is much wider than the 20 feet indicated in the design plans but is completely devoid of vegetation. It was noted that the roadway embankment of County Road 673 (in the vicinity of the downstream slope toe) is much higher than the dam embankment (about 25 feet just below the spillway) and effectively forms an additional embankment structure roughly paralleling the main embankment axis.

c. Appurtenant Structures

The three-sided concrete spillway is in a satisfactory condition with only minor cracking and surface spalling but the stone masonry walls of the older highway bridge immediately below the spillway are in an advanced stage of deterioration. The original ashlar masonry has been repaired with concrete blocks which have pulled loose and the mortar joints are open. The concrete wingwalls are only vestiges of their original shape with many parts missing or broken loose from their supports. The sharp-crested weirs on the spillway were submerged and could not be examined closely but the crest appears level with no evidence of differential settlement. Several new timber stoplogs have been recently installed in the sluice ways on each side of the inlet. It could not be determined how the stoplogs are removed from the lower righthand opening. The small steel I-beams which formerly supported the bridge deck slab are rusty and add only secondary lateral support to the abutment walls.

There are several sections of small water mains in and around the spillway but it could not be determined if any were operable.

d. Reservoir

Kirkwood Lake has a well-established shore line with numerous homes along the north boundary. On the south, the storage and switching yards of the PATCO commuter line occupies much of the frontage. The lake is clear of debris up to its headwaters where Cooper River and Millard Creek jointly feed the reservoir. It was noted that there are several small dams immediately upstream (see Section 5).

e. Downstream Channel

The discharge from the dam flows through a 8' x 15' elliptical C.M.P. culvert under

the Route 673 embankment. The channel runs parallel to the railway embankment and is straight and fairly clear of obstructions. However, it makes a sharp left turn approximately one-tenth of a mile downstream from the highway and passes through a bridge under the railroad. The railroad bridge has a rectangular opening with a span of 21 feet and a height of opening to water surface of 5 feet. Further downstream the highway culvert under Chews Landing Road is almost completely silted up. The only facility in the downstream flood plain is a sewage disposal plant 1.3 miles below the dam.



## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

Operational procedures were not observed by the inspection team. As the present owners could not be located, maintenance responsibility or operational procedures undertaken in the past (except for dewatering the lake several years ago) remain unknown.

### 4.2 MAINTENANCE OF DAM

There has apparently been little or no continual maintenance of this dam.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

The only operational facilities are the two stop-log gates in the sides of the spillway. It appears they are opened only during de-watering operations for reservoir maintenance and were last employed in 1974 by the Voorhees Township Jaycees.

### 4.4 DESCRIPTION OF WARNING SYSTEM IN EFFECT

There is no formalized warning system in effect as the dam has not been overtopped since 1940. However, it is positioned on the municipal boundary which could be the cause of possible jurisdictional problems.

### 4.5 EVALUATION OF OPERATIONAL ADEQUACY

Present safeguards are deemed to be adequate in view of performance record and the lack of hazards relating to the dam. However, it is felt that the ownership responsibility of maintenance should be clarified in the future by local and state authorities notwithstanding the fact that the structure is presently operating satisfactorily.



## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

#### a. Design Data

In accordance with the criteria in the Recommended Guidelines for Safety Inspection of Dam, it has been determined that the dam at Kirkwood Lake is small in size and is placed in the significant hazard category. Accordingly, the spillway design flood (SDF) was selected by the inspection team to be the 100-year frequency event. The inflow hydrograph was calculated utilizing precipitation data from Technical Paper 40 and NOAA Technical Memorandum NWS Hydro-35. The inflow hydrograph and routing through the reservoir were performed by the HEC-1 computer program. Peak inflow to the reservoir was 4,505 cfs which when routed through the reservoir was reduced to 3,647 cfs. The spillway capacity before overtopping is approximately 918 cfs, thus the spillway will accommodate only 25% of the design flood.

#### b. Experience Data

Records indicate that the dam has been overtopped several times in the past. In December 1940, the dam was overtopped by 5 feet and the embankment failed in three places. There is a water quality gage located at the site. Original design calculations indicate a spillway capacity of 885 cfs and according to the Corps of Engineers, the Hydrology Coordinating Committee of the Delaware River Basin Commission has adopted a  $Q_{100}$  of 2,500 cfs at this site.

#### c. Visual Observations

It appears the dam is protected to a great degree by the highway embankment of White Horse Road.

#### d. Overtopping Potential

Employing the discharge and spillway capacities contained herein, overtopping of more than three

feet would occur in the event of the design storm. Moreover the dam has been overtopped several times in the past and thus it is felt there is considerable potential for future overtopping.

e. Drawdown

It would take approximately 13 hours to dewater the lake utilizing the 3' x 5' lower gate. The invert of this gate is 8.5' below the crest elevation and as previously reported, it could not be ascertained how the lower portions of the stoplogs could be pulled.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

The concrete spillway, although buttressed against the old stone masonry abutment walls is in no immediate danger of collapse unless the embankment is scoured out on each side. Further, during most severe flooding conditions, there is apparently a backwater condition caused by the partially-blocked elliptical CMP culvert under the roadway embankment just 100 feet downstream. However, surface run-off from the crest is slowly scouring out the backslope fill behind the bridge wingwalls and together with the two storm drains from the railroad property have created a stilling basin between the dam and the roadway embankment.

A major portion of the dam is of no structural concern as the downstream slopes are completely backfilled up to dam crest elevation and surcharged by the highway embankment.

#### b. Design and Construction Data

Sufficient design data was available from the 1941 Application permit to evaluate the concrete spillway. Little can be deduced relative to the structural stability of the old bridge abutments especially regarding the in-situ foundation conditions. It is very possible that the bridge is constructed on timber piling (in view of the lack of differential settlement). As long as the spillway is laterally braced by the bridge substructure, its structural condition is satisfactory.

#### c. Operating Records

No formal records exist. As previously stated, the spillway appears to have functioned satisfactorily as an uncontrolled outlet since its 1941 reconstruction. There are no recorded instances of overtopping since that date.

d. Post Construction Changes

There have been no modifications to the hydraulic elements since 1941. However, the surrounding area has undergone considerable change with the addition of the downstream highway embankment and bridge over the railroad, the addition of the railroad sidings, relocated trackage, marshalling yard drainage and the abandonment of the local street over the dam crest.

e. Seismic Stability

The bridge has an adequate factor of safety against static loadings and experience indicates that it will therefore have adequate stability against Seismic Zone 1 dynamic loadings.



SECTION 7 - ASSESSMENTS/RECOMMENDATIONS/  
REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety

Subject to the inherent limitations of the Phase I visual inspection, Kirkwood Lake Dam is classified as being in a sound and overall fair condition insofar as its embankment structure is concerned but the spillway bridge abutments at the main discharge outlet are in need of repair. No seriously detrimental findings were revealed in this inspection to render a questionable judgement as to the present structural stability. The concrete spillway is inadequate hydraulically, being able to accommodate approximately 25% of the 100 year design flood. The overtopping potential is considerable due to the hydraulically inadequate spillway and the ease with which the elliptical CMP outlet, 100 feet downstream, can be blocked with debris.

b. Adequacy of Information

The information gathered for the Phase I inspection is deemed to be adequate regarding the structural stability of the dam except for the lack of detailed information regarding the bridge foundations. No surveys or inspections have been recorded since 1961 and the dam has undergone deterioration since that time.

c. Urgency

It is recommended that the remedial measures set forth below be taken under advisement in the near future.

d. Necessity for Further Study

Due to the downgraded significant hazard classification and the fact that only moderate

downstream property damage is likely in case of a failure, further engineering studies, under the purview of the P.L. 92-367, are believed to be unnecessary.

## 7.2 RECOMMENDATIONS/REMEDIAL MEASURES


It is recommended that the ownership and responsibility for maintenance be clarified as a collapse could present a legal problem regarding responsibility.

### a. Alternatives

- The downstream slopes of the dam embankment in the vicinity of the bridge wingwalls should be regraded, compacted and topped with suitable slope protection.
- The trees should be removed from the dam crest in the vicinity of the spillway and the disturbed areas regraded, compacted and seeded.
- Heavy stone should be placed in the downstream stilling basin in selected areas to prevent further scouring and preclude the undermining of the bridge structure.
- Patch the spalled and deteriorated concrete surfaces and stone masonry of the bridge walls.
- The crest width should be increased at each side of the spillway and seeded or protected from surface erosion.


### b. O&M Maintenance and Procedures

The owners should upgrade O&M procedures by issuing check lists for periodic inspections and institute a system of record keeping for severe storms.



**FIGURE 1**  
**REGIONAL**  
**VICINITY MAP**  
**SCALE 1:24,000**





**GENERAL PLAN**

**FIGURE 2**







FIGURE 3



INLET ELEVATION

Not to Scale




FIGURE 4

Check List  
Visual Inspection  
Phase 1

Name Dam Kirkwood Lake County Camden State New Jersey Coordinators NJDEP

Date(s) Inspection 1 May 79 Weather Clear Temperature 60 F

Pool Elevation at Time of Inspection 56± M.S.L. Tailwater at Time of Inspection 48± M.S.L.

Inspection Personnel:

K. Jolls L. Baines

E. Simone

K. Greenfield

L. Baines Recorder

CONCRETE/MASONRY DAMS  
(SPILLWAY BRIDGE)

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

SEE PAGE ON LEAKAGE

STRUCTURE TO  
ABUTMENT/EMBANKMENT  
JUNCTIONS

Satisfactory

Poorly defined  
abutment zone.

DRAINS

None

No visible method of  
dewatering lake except  
stop logs.

WATER PASSAGES

None

FOUNDATION

No backslopes - top of dam is at  
toe of downstream roadway embankment  
Structural stability no problem.

West portion of embankment  
ill-defined.



CONCRETE/MASONRY DAMS  
(Spillway Bridge)

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Concrete wingwalls are badly broken up and demolished	Much is beyond repair and should be replaced.
STRUCTURAL CRACKING	Severe (in masonry joints)	
VERTICAL AND HORIZONTAL ALIGNMENT	Poor - no regular geometry	Exposed steel I-beams over spillway (Superstructure missing)
MONOLITH JOINTS	None	
CONSTRUCTION JOINTS	None	

# EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None Observed Crest sand with trace of silt & clay (little cohesion). No protection.	Top of dam grade very irregular. Eroded by dirt bike tracks and run-off from roadway slopes to the South.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None Observed	Downstream toe covered by road embankment.
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Embankment upstream slope to left of spillway very steep. Downstream slope severely eroded (towards headwall of drains under RR embankment.)	Slope paving required at wingwall swales.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Very irregular	Spillway is at low point on crest.
RIPRAP FAILURES	No riprap	Some small areas eroded on upstream slopes.

# EMBANKMENT

## VISUAL EXAMINATION OF

EXCESSIVE SHRUB GROWTH,  
TREES, ETC.

## OBSERVATIONS

Trees on upstream  
slope (do not remove  
except adjacent to  
spillway).

## REMARKS OR RECOMMENDATIONS

No discernible embankment  
(no downstream slopes  
except at elliptical pipe  
under roadway embankment).

FUNCTION OF EMBANKMENT  
AND ABUTMENT, SPILLWAY  
AND DAM

Satisfactory

## ANY NOTICEABLE SEEPAGE

No

## STAFF GAGE AND RECORDER

None (re H & H)

Water quality  
gage.

## DRAINS

One

OUTLET WORKS (Spillway Bridge)

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Old masonry walls along outlet. Masonry in very poor condition (badly spalled). ↑	Concrete block placed over stone masonry in some areas.
INTAKE STRUCTURE	Concrete crest in satisfactory condition.	
OUTLET STRUCTURE		
OUTLET CHANNEL	Natural stilling basin between outlet & road embankment 100' west.	
EMERGENCY GATE	3'x5' gate bottom right of box spillway. Appears inoperable.	See plans for gate size on other wall (submerged)



UNCATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	11' x 19' concrete drop inlet (satisfactory condition)	Crest appears straight & true (no chipping or diff. settlement).
APPROACH CHANNEL	Main body of reservoir	
DISCHARGE CHANNEL	Clear	Flow discharges into CMP under highway embankment immediately downstream.
BRIDGE AND PIERS	See outlet works	Several water pipes at upstream face. (No man- holes or connections located).

⑦

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION			REMARKS OR RECOMMENDATIONS
VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS		
	None +		
OBSERVATION WELLS	None		
WEIRS	None		
PIEZOMETERS	None		
OTHER	Water quality gage.		

(2)

RESERVOIR

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

OBSERVATIONS

SLOPES

Flat, gentle slopes on right,  
with slightly steeper grade  
on left.

SEDIMENTATION

Reservoir heavily silted up. (Lilies  
growing in some areas.) Shoreline  
well established. Heavily wooded  
right down to waters edge. Appears  
to have been cleaned periodically.



DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	8'x15' elliptical CMP under Rt. 673 embankment. Railroad bridge further downstream (span-20't, 5' freeboard) Channel parallels RR embankment.	1 or 2 feet of silt blocking CMP.

SLOPES

Flat, very irregular,  
wooded, undeveloped area.  
All homes above flood elevation

APPROXIMATE NO.  
OF HOMES AND  
POPULATION

None

Only sewage plant in Somer  
dale could be affected.

Note:

Dam appears to have been overtopped  
just to the right of the spillway  
(possibly from surface drainage  
from RR yard.)

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Available (NJDEP)
REGIONAL VICINITY MAP	Available (U.S.G.S. Quad)
CONSTRUCTION HISTORY	Available (NJDEP)
TYPICAL SECTIONS OF DAM	Not available
HYDROLOGIC/HYDRAULIC DATA	Some available (NJDEP and USGS)
OUTLETS - PLAN	Available (NJDEP) - partially
- DETAILS	Available (NJDEP)
-CONSTRAINTS	Not available
-DISCHARGE RATINGS	Not Available
RAINFALL/RESERVOIR RECORDS	Not Available

ITEM

REMARKS

SPILLWAY PLAN

SECTIONS

None

DETAILS

None

OPERATING EQUIPMENT  
PLANS & DETAILS

None

ITEM	REMARKS
DESIGN REPORTS	Not Available
GEOLOGY REPORTS	Not available
DESIGN COMPUTATIONS	Not available
HYDROLOGY & HYDRAULICS	Not available
DAM STABILITY	Limited available (NJDEP)
SEEPAGE STUDIES	Not available
MATERIALS INVESTIGATIONS	Not available
BORING RECORDS	"
LABORATORY	"
FIELD	"
POST-CONSTRUCTION SURVEYS OF DAM	Not available
BORROW SOURCES.	Not available



ITEM	REMARKS
MONITORING SYSTEMS	None
MODIFICATIONS	None
HIGH POOL RECORDS	None
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Available (partial)
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Available (NJDEP) (partial) Available (NJDEP) (Partial) Not available
MAINTENANCE OPERATION RECORDS	Some Available



May, 1979

View of Spillway Structure



May, 1979



View of CMP Under Rt. 673 Embankment

May, 1979



View of Stilling Basin

May, 1979

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 5.14 sq. mi.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): + 55.81 (92 AF)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): +59.81 (226 AF)

ELEVATION MAXIMUM DESIGN POOL: Unknown

ELEVATION TOP DAM: + 59.81

CREST: \_\_\_\_\_

- a. Elevation +59.81
- b. Type Earth embankment
- c. Width Varies
- d. Length 250
- e. Location Spillover None
- f. Number and Type of Gates 2 sets of 3' 0" stoplogs

OUTLET WORKS: \_\_\_\_\_

- a. Type 3-sided concrete drop inlet
- b. Location left abutment
- c. Entrance inverts +55.81
- d. Exit inverts +47.3
- e. Emergency draindown facilities None

HYDROMETEOROLOGICAL GAGES: None

- a. Type \_\_\_\_\_
- b. Location \_\_\_\_\_
- c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: 918 c.f.s.(spillway capacity)



BY D.J.M. DATE 9-79

LOUIS BERGER &amp; ASSOCIATES INC.

SHEET NO. A1 OF

CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

KIRKWOOD LAKE DAMPROJECT C234

SUBJECT \_\_\_\_\_

length of longest watercourse = 2.3 miles = 12,144 ft.  
 $\Delta H = 40'$

$$\therefore t_c = \left( \frac{11.9 \times 2.3^3}{40} \right)^{0.385} = 1.64 \text{ hours}$$

Alternate method :

$$\text{Slope along watercourse} = \frac{40 \times 100}{12,144} = 0.33\%$$

Assume velocity = 1.5 ft. s<sup>-1</sup>

$$\therefore t_c = \frac{12,144}{1.5 \times 3600} = 2.25 \text{ hours}$$

$$\text{Overland flow} \quad \text{Slope} = \frac{80 \times 100}{2000} = 4\%$$

Assume velocity = 2 ft. s<sup>-1</sup>

$$\therefore t' = \frac{2000}{2 \times 3600} = 0.28 \text{ hours}$$

$$\therefore t_c = t + t' = 2.53 \text{ hours}$$

Use  $t_c = 2.1$  hours

$$\therefore t_p = \frac{0.25}{2} + 0.6 \times 2.1 = 1.39 \text{ hours}$$

$$Q_p = \frac{484 \times 5.14}{1.39} = 1790 \text{ cfs}$$

BY D. J. M. DATE 9-79

CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT \_\_\_\_\_

LOUIS BERGER &amp; ASSOCIATES INC.

KIRKWOOD LAKE DAMSHEET NO. A2 OF \_\_\_\_\_PROJECT C-234Unitgraph:

<u>Time</u> <u>(hours)</u>	<u>T/T<sub>p</sub></u>	<u>Dimensionless</u> <u>Ordinate (DO)</u>	<u>Q (cfs)</u> <u>= Q<sub>p</sub> x DO</u>
0.25	0.18	0.06	107
0.50	0.36	0.22	394
0.75	0.54	0.49	877
1.00	0.72	0.79	1414
1.25	0.90	0.97	1736
1.50	1.08	0.99	1772
1.75	1.26	0.87	1557
2.00	1.44	0.71	1271
2.25	1.62	0.54	966
2.50	1.80	0.42	752
2.75	1.98	0.32	573
3.00	2.16	0.25	447
3.25	2.34	0.19	340
3.50	2.52	0.14	251
3.75	2.70	0.11	197
4.00	2.88	0.08	143
4.25	3.06	0.06	107
4.50	3.24	0.05	89
4.75	3.42	0.04	72
5.00	3.60	0.03	54
5.25	3.78	0.025	45
5.50	3.96	0.019	34

BY D. J. M. DATE 6-79

LOUIS BERGER &amp; ASSOCIATES INC.

SHEET NO. 13 OF     CHKD. BY      DATE     SOUTH GROUP DAMSPROJECT C 234SUBJECT     

Precipitation data from T.P. 40 & NOAA Technical Memorandum  
NWS HYDRO - 35 (See depth duration curve over leaf)

Time	Precipitation	$\Delta$	Rearrange $\Delta$
0.25	1.7	1.7	0.06
0.50	2.4	0.7	0.06
0.75	2.8	0.4	0.06
1.00	3.1	0.3	0.07
1.25	3.4	0.3	0.08
1.50	3.7	0.3	0.09
1.75	3.86	0.16	0.11
2.00	4.00	0.14	0.14
2.25	4.11	0.11	0.30
2.50	4.22	0.11	0.30
2.75	4.31	0.09	0.70
3.00	4.40	0.09	1.70
3.25	4.49	0.09	0.40
3.50	4.57	0.08	0.30
3.75	4.64	0.07	0.16
4.00	4.71	0.07	0.11
4.25	4.78	0.07	0.09
4.50	4.84	0.06	0.09
4.75	4.90	0.06	0.07
5.00	4.96	0.06	0.07
5.25	5.02	0.06	0.06
5.50	5.08	0.06	0.06
5.75	5.14	0.06	0.06
6.00	5.20	0.06	0.06



BY D. J. M. DATE 1-11

SUBJECT

SHEET NO.


OF A4

CHKD. BY DATE

DEPTH DURATION CURVE

JOB NO. C227

T.P. 40 & NOAA Tech. Memo NWS - HYRO 35





BY D.J.M. DATE 6-79

LOUIS BERGER &amp; ASSOCIATES INC.

SHEET NO. A5 OF     CHKD. BY      DATE     KIRKWOOD LAKE DAMPROJECT 5030SUBJECT Spillway discharge capacity

Spillway discharge :

flow over spillway  
crest  $L = 37'$ 

<u>H</u>	<u>C</u>	<u>Q</u>
1	3.1	115
2	3.1	324
3	3.1	596
4	3.1	918
5	3.1	1282
6	3.1	1686
7	3.1	2124
8	3.1	2595

flow over dam  
 $L = 250'$ 

<u>H</u>	<u>C</u>	<u>Q</u>
0	2.8	0
1	2.8	700
2	2.8	1980
3	2.8	3637
4	2.8	5600


 $\Sigma Q$   
(cfs)

115
324
596
918
1982
3666
5761
8195

The spillway capacity calculated above does not include the two low level openings built into the sides of the spillway structure. As there is no guarantee that they will be open under flood conditions.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DOD

KIRKWOOD LAKE DAM  
STAGE DISCHARGE CURVE



46 0706

K·E 10 X 10 TO THE INCH • 7 X 10 INCHES  
KEUFFEL & ESSER CO. MADE IN U.S.A.

BY D. J. M. DATE 6-79

CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.

KIRKWOOD LAKE DAM


SHEET NO. A7 OF \_\_\_\_\_

PROJECT C234

Surcharge storage:

Area of lake @ El. 55.81 = 31 acres

Area of 70' contour = 217.1 acres



Increment in volume  $\Delta V = (x + \Delta x)Y$

Height in feet  
above spillway  
crest (feet)

Surcharge  
storage  
(acre feet)

0

1

32

2

65

3

99

4

134

5

177

6

237

7


315

8

411



KIRKWOOD LAKE DAM  
STAGE STORAGE CURVE





BY D. J. M. DATE 7-79

LOUIS BERGER &amp; ASSOCIATES INC.

SHEET NO. 19 OF

CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

KIRKWOOD LAKE DAMPROJECT C 234SUBJECT Approximate drawdown calculationAvailable head  $\approx 8.5'$ 

Storage @ normal pool = 92 acre feet

Assume drawdown in two equal stages with no inflow or tailwater conditions.

stage i)

$$H = 6.4'$$

$$Q \approx 117 \text{ cfs}$$

$$\therefore \text{time} \approx \frac{92 \times 43560}{117 \times 2 \times 3600}$$

$$= 4.76 \text{ hours}$$

stage ii)

$$H = 2.13'$$

$$Q = 68 \text{ cfs}$$

$$\therefore \text{time} \approx \frac{92 \times 43560}{2 \times 68 \times 3600}$$

$$= 8.19 \text{ hours}$$

$$\leq \text{time} \approx (4.76 + 8.19) \approx 13 \text{ hours}$$

BY D.J.M. DATE \_\_\_\_\_  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

# LOUIS BERGER & ASSOCIATES INC.

KIRKWOOD LAKE DAM

SHEET NO. A10 OF \_\_\_\_\_  
 PROJECT 0-254

KIRKWOOD LAKE DAM  
 BY D.J.M.  
 JUNE 21 1979

## JOB SPECIFICATION

NG	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
100	0	15	0	0	0	0	0	0	0
				JOPER	NWT				
				3	0				

## SUR-AREA RUNOFF COMPUTATION

### INFLOW HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME
1	0	0	0	0	0	1

### HYDROGRAPH DATA

IHYDG	IUG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
0	-1	5.14	0.0	5.14	0.0	0.0	0	0	0

### PRECIP DATA

NP	STORM	DAJ	CAK
24	0.0	0.0	0.0

### PRECIP PATTERN

0.06	0.06	0.06	0.07	0.08	0.09	0.11	0.14	0.30	0.30
0.70	1.70	0.40	0.30	0.16	0.11	0.09	0.09	0.07	0.07
0.06	0.06	0.06	0.06						

### LOSS DATA

STRKR	DLTKR	RTIOL	ERAIN	STRKS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0.0	0.0	1.00	0.0	0.0	1.00	1.50	0.33	0.0	0.0

### GIVEN UNIT GRAPH, NUF66= 22

107.	394.	877.	1414.	1736.	1772.	1557.	1271.	966.	752.
573.	447.	340.	251.	197.	143.	107.	89.	72.	54.
45.	34.								

UNIT GRAPH TOTALS 13198. CFS OR 1.00 INCHES OVER THE AREA

### RECESSION DATA

STRTQ= 0.0 GRCSN= 0.0 RTIOR= 1.00

### END-OF-PERIOD FLOW

TIME	RAIN	EXCS	COMP Q
1	0.06	0.00	0.
2	0.06	0.00	0.
3	0.06	0.00	0.
4	0.07	0.00	0.
5	0.08	0.00	0.
6	0.09	0.00	0.
7	0.11	0.00	0.
8	0.14	0.00	0.

BY DJM DATE \_\_\_\_\_  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.

KIRKWOOD LAKE DAM

SHEET NO. 111 OF \_\_\_\_\_  
PROJECT C-234

9	0.30	0.00	0.
10	0.30	0.00	0.
11	0.70	0.42	45.
12	1.70	1.62	339.
13	0.40	0.33	1243.
14	0.30	0.23	2171.
15	0.16	0.09	3409.
16	0.11	0.04	4259.
17	0.09	0.02	4505.
18	0.09	0.02	4188.
19	0.07	0.00	3592.
20	0.07	0.00	2894.
21	0.06	0.00	2304.
22	0.06	0.00	1796.
23	0.06	0.00	1401.
24	0.06	0.00	1072.
25	0.0	0.0	810.
26	0.0	0.0	622.
27	0.0	0.0	462.
28	0.0	0.0	351.
29	0.0	0.0	279.
30	0.0	0.0	221.
31	0.0	0.0	171.
32	0.0	0.0	138.
33	0.0	0.0	95.
34	0.0	0.0	31.
35	0.0	0.0	16.
36	0.0	0.0	6.
37	0.0	0.0	3.
38	0.0	0.0	1.
39	0.0	0.0	1.
40	0.0	0.0	0.
41	0.0	0.0	0.
42	0.0	0.0	0.
43	0.0	0.0	0.
44	0.0	0.0	0.
45	0.0	0.0	0.
46	0.0	0.0	0.
47	0.0	0.0	0.
48	0.0	0.0	0.
49	0.0	0.0	0.
50	0.0	0.0	0.
51	0.0	0.0	0.
52	0.0	0.0	0.
53	0.0	0.0	0.
54	0.0	0.0	0.
55	0.0	0.0	0.
56	0.0	0.0	0.
57	0.0	0.0	0.
58	0.0	0.0	0.
59	0.0	0.0	0.
60	0.0	0.0	0.
61	0.0	0.0	0.
62	0.0	0.0	0.
63	0.0	0.0	0.
64	0.0	0.0	0.
65	0.0	0.0	0.
66	0.0	0.0	0.
67	0.0	0.0	0.
68	0.0	0.0	0.
69	0.0	0.0	0.



PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL
4505.	1508.	377.	362.	36224.
	748.	2.73	2.73	2.73
		749.	749.	749.

## HYDROGRAPH ROUTING

[illegible]



BY DJM DATE \_\_\_\_\_  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.

KIRKWOOD LAKE DAM

SHEET NO. A13 OF \_\_\_\_\_  
PROJECT 9-23-

3	0.	0.	0.
4	0.	0.	0.
5	0.	0.	0.
6	0.	0.	0.
7	0.	0.	0.
8	0.	0.	0.
9	0.	0.	0.
10	0.	0.	0.
11	0.	22.	2.
12	4.	192.	15.
13	18.	691.	64.
14	48.	1607.	216.
15	97.	2790.	583.
16	156.	3834.	1452.
17	203.	4382.	2714.
18	229.	4347.	3448.
19	236.	3890.	3647.
20	230.	3243.	3465.
21	216.	2599.	3076.
22	200.	2050.	2615.
23	183.	1598.	2158.
24	168.	1237.	1766.
25	155.	941.	1430.
26	143.	716.	1139.
27	133.	542.	909.
28	124.	406.	822.
29	114.	315.	734.
30	105.	250.	650.
31	96.	196.	574.
32	88.	154.	510.
33	81.	116.	450.
34	73.	63.	391.
35	66.	24.	335.
36	60.	11.	293.
37	54.	5.	257.
38	50.	2.	226.
39	45.	1.	198.
40	41.	0.	174.
41	38.	0.	153.
42	35.	0.	134.
43	32.	0.	117.
44	30.	0.	108.
45	28.	0.	100.
46	26.	0.	93.
47	24.	0.	86.
48	22.	0.	80.
49	21.	0.	75.
50	19.	0.	69.
51	18.	0.	64.
52	17.	0.	60.
53	15.	0.	55.
54	14.	0.	51.
55	13.	0.	48.
56	12.	0.	44.
57	11.	0.	41.
58	11.	0.	38.
59	10.	0.	35.
60	9.	0.	33.
61	9.	0.	31.
62	8.	0.	28.
63	7.	0.	26.

BY D.J.M. DATE \_\_\_\_\_  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

# LOUIS BERGER & ASSOCIATES INC.

KIRKWOOD LAKE DAM

SHEET NO. 116 OF \_\_\_\_\_  
 PROJECT 5-238

64	7.	0.	24.
65	6.	0.	23.
66	6.	0.	21.
67	5.	0.	20.
68	5.	0.	18.
69	5.	0.	17.
70	4.	0.	16.
71	4.	0.	15.
72	4.	0.	13.
73	3.	0.	13.
74	3.	0.	12.
75	3.	0.	11.
76	3.	0.	10.
77	3.	0.	9.
78	2.	0.	9.
79	2.	0.	8.
80	2.	0.	7.
81	2.	0.	7.
82	2.	0.	6.
83	2.	0.	6.
84	2.	0.	6.
85	1.	0.	5.
86	1.	0.	5.
87	1.	0.	4.
88	1.	0.	4.
89	1.	0.	4.
90	1.	0.	4.
91	1.	0.	3.
92	1.	0.	3.
93	1.	0.	3.
94	1.	0.	3.
95	1.	0.	2.
96	1.	0.	2.
97	1.	0.	2.
98	1.	0.	2.
99	1.	0.	2.
100	0.	0.	2.

SUM 36202.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	3647.	1402.	377.	362.	36202.
INCHES		2.54	2.73	2.73	2.73
AC-FT		695.	748.	748.	748.

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

## RUNOFF SUMMARY, AVERAGE FLOW

		PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
HYDROGRAPH AT	1	4505.	1508.	377.	362.	5.14
ROUTED TO	11	3647.	1402.	377.	362.	5.14